| 2  |    | On page 9 of the report filed at Volume II, Tab 19, Hydro states that the proactive   |
|----|----|---|
| 3  |    | refurbishment and/or replacement of anchors and footings is common among              |
| 4  |    | utility companies. Provide support for this statement.                                |
| 5  |    |   |
| 6  |    |   |
| 7  | A. | This statement is meant to indicate that it is good engineering practice to           |
| 8  |    | proactively refurbish deteriorated infrastructure to prevent its failure, rather than |
| 9  |    | reactively refurbish after a failure occurs. The statement that it is common practice |
| 10 |    | is based on conversations with other utilities. However, Hydro believes, in the case  |

of transmission tower anchors and footings, this proactive refurbishment is

necessary to prevent tower failures and the associated safety hazards and

**Project C-44, Refurbish Anchors and Footings** 

1

11

12

13

unplanned outages.

Q.