

1 Q. C-5; Volume I, Tab 2: Surge Tank 3 Refurbishment – Bay D’Espoir, page A40: the  
2 Hatch report states that: *“It is our opinion the CP system is not functional and*  
3 *poses a hazard to the turbine runner and other components.”* It is then  
4 recommended to: *“Remove the existing CP system and all associated components*  
5 *and supporting system.”*

6 How will Hydro address the recommendation that the existing CP system and all  
7 associated components and supporting system be removed?  
8  
9

10 A. Hydro will address the recommendation to remove the existing CP system and all  
11 associated components as part of the scope of work for a separate capital project  
12 which is in the capital plan for 2015 under the heading “Refurbish Surge Tanks –  
13 Bay d’Espoir”.