

1 Q. Please provide the failure rate for the specific cable type you are using in the SOBI.

2

3

4 A. Hydro is not aware of any mass impregnated cable failures caused by
5 manufacturing defects.

6

7 Please refer to Hydro's response to DD-NLH-067, Attachment 1, page 4.