

1 Q. With reference to IC-NLH-096, if the Hardwoods gas turbine was not operated
2 under other than normal operating circumstances during this 2 month period, has
3 Hydro examined whether the December 2015 inspection was properly conducted
4 and whether a review of the inspection protocol, beyond increasing to a semi-
5 annual frequency, is needed?
6
7

8 A. Hydro has examined the borescope inspection protocol and is satisfied that the
9 inspection was conducted properly. Hydro has reviewed the borescope inspection
10 with the service provider and although a small crack was noted, it was within
11 acceptable limits as published in Original Equipment Manufacturer manuals and
12 service bulletins and was deemed serviceable for the remainder of the 2016 winter
13 operating season.