

1 Q. Further to the response to PUB-NLH-036, when was it determined that the
2 insulating blankets on end B of the Stephenville Gas Turbine had to be replaced and
3 why was it not completed by December 1, 2013? In the reply include the
4 completion date for this replacement.

5

6

7 A. See Hydro's response to PUB-NLH-072.