## Page 1 of 1

1	Q.	Reference: Gas Turbine Failure Analysis - Final Report, January 11, 2017, page 5, line
2		5. Explain why the overhaul facility did not receive the Hardwoods engine until
3		August 3, 2016, approximately 6 months after the failure.
4		
5		
6	Α.	Please see the timeline below, from the time of failure to the shipment of the
7		Hardwoods engine <sup>1</sup> to the overhaul facility:
8		• February 8, 2016 – Failure of the engine;
9		• February 14, 2016 – Installation of loaner engine complete;
10		<ul> <li>March 2016 to May 2016 – Budget preparation internal Hydro Review;</li> </ul>
11		<ul> <li>May 12, 2016 – Hydro Board of Directors' approval received;</li> </ul>
12		May 19, 2016 – Supplemental Capital Application filed with Board of
13		Commissioners of Public Utilities;
14		<ul> <li>May 24, 2016 – Tender for engine overhaul released;</li> </ul>
15		<ul> <li>June 7, 2016 – Tender for engine overhaul closed;</li> </ul>
16		<ul> <li>June 15, 2016 – Board of Commissioners of Public Utilities approval</li> </ul>
17		received;
18		<ul> <li>July 19, 2016 – Contract awarded to Alba Power;</li> </ul>
19		<ul> <li>July 27, 2016 – Engine shipped to Alba Power overhaul facility; and</li> </ul>
20		• August 3, 2016 – Engine arrived at Alba Power overhaul facility.