Reference: Application, 2023 Capital Expenditures Overview, page 5 1 Q. 2 It is stated 3 Increased project contingency due to the likelihood of additional required scope 4 of work that may be identified following disassembly and inspection of the unit, 5 including possible requirements to remove rotor poles for cleaning and 6 completing stator repairs. 7 Why is this contingency being added now rather than at the time the original budget estimate 8 was developed? 9 10 Newfoundland and Labrador Hydro ("Hydro") developed the estimate for this supplemental 11 A. application¹ based on its history of work at the Upper Salmon Hydroelectric Generating Station 12 ("Upper Salmon Station") and similar projects completed for Unit 7 at the Bay d'Espoir 13 Hydroelectric Generating Facility. With this knowledge, a contingency of 10% was determined to 14 be appropriate. The additional contingency has since been added due to unforeseen issues 15 identified during regular inspections² of the generator at the Upper Salmon Station and the 16 17 likelihood of additional scope work following generator disassembly.

¹ "Application for Approval to for Rotor Rim Shrinking and Stator Recentering at the Upper Salmon Hydroelectric Generating Station," Newfoundland and Labrador Hydro, April 26, 2022, approved as per *Public Utilities Act*, RSNL 1990, c. P-47, Board Order No. P.U. 18(2022), Board of Commissioners of Public Utilities, May 20, 2022.

² These inspections were recommended by the original equipment manufacturer after discovering the initial mechanical damage to the Upper Salmon generator.