## 2 3

8 9 10

11 12 13

14

Α.

20 21 22

> 23 24 25

26 27 28

29

30

**5.1 Port Union Building Replacement** 

- Page 3. Newfoundland Power states a visual condition assessment of the Q. facility was completed in 2024.
  - a) Please provide details of the steps involved in a visual condition assessment.
  - b) Is the condition assessment referenced in the Conclusion on Page 11 the same as the visual condition assessment? If not, when was the condition assessment completed?
  - c) How has Newfoundland Power addressed the concerns identified in the condition assessment(s) since completion?
  - a) A visual condition assessment consists of a thorough walk through of the facilities interior and exterior observing the condition of the following six asset components: (i) superstructure; (ii) building envelope; (iii) architectural systems; (iv) mechanical systems; (v) electrical systems; and (vi) sitework. The deficiencies noted in report 5.1 Port Union Building Replacement were easily visible during execution of the condition assessment. The deficiencies observed were subsequently used to develop report 5.1 Port Union Building Replacement that is included in the 2025 Capital Budget Application.
  - b) The condition assessment referenced in the Conclusion on Page 11 is the same as the visual condition assessment.
  - c) Newfoundland Power utilizes the *Additions to Real Property* program to mitigate minor general properties deficiencies as they are discovered. The concerns identified during the condition assessment cannot be addressed utilizing the Additions to Real *Property* program as the capital investment required is substantial. As outlined in the 5.1 Port Union Building Refurbishment report, the least cost alternative to address the deteriorated condition of the building is to replace the facility in 2025 and 2026.