

1 Q. Further to NP-98, with respect to the replacement of manufacturer non-  
2 supported equipment, answer the following questions or provide the  
3 information appropriate on each budget item identified below:  
4

<i>Budget Item</i>	<i>Amount</i>	<i>Description</i>
B-8	\$863,000	Replace Exciter Unit 1 – Cat Arm (installed 1984)
B-11	\$606,000	Replacement of Governor Control Upper Salmon (installed 1982)
B-68	\$556,000	Replace UHF Radio – Upper Salmon (20 years old)

5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15 How much would it have cost for an additional set of spares (one additional  
16 for each type)? Estimate the cost if detailed information is not available.  
17  
18

19 A.

<i>Budget Item</i>	<i>Amount</i>	<i>Description</i>
B-8	\$863,000	Replace Exciter Unit 1 – Cat Arm (installed 1984)

20  
21  
22  
23 An additional set of spares would have cost \$81,592 in 1984.  
24

25 Spare cards are no longer available from the manufacturer. The  
26 manufacturer will repair the cards only if the components are available.

---

1	<b><i>Budget Item</i></b>	<b><i>Amount</i></b>	<b><i>Description</i></b>
2	B-11	\$606,000	Replacement of Governor Control
3			Upper Salmon (installed 1982)

4

5 An additional set of spares would have cost \$15,528 in 1982.

6

7 Spare cards are no longer available from the manufacturer. The  
8 manufacturer will repair the cards only if the components are available.

9

10	<b><i>Budget Item</i></b>	<b><i>Amount</i></b>	<b><i>Description</i></b>
11	B-68	\$556,000	Replace UHF Radio – Upper
12			Salmon (20 years old)

13

14 As stated in our response to NP-98 B-68 Replace UHF Radio (Upper  
15 Salmon) part (g), the manufacturer no longer provides spares for this  
16 equipment. There is no estimate available for the cost of an additional set of  
17 spares at the time of discontinuance in 1990.