

1 Q. 28.0 RE: p. B-38 Replace Insulators - English Harbour West (\$669,000)

2

3 28.1 What is the current status of the insulator replacement program? Is
4 there a plan with regard to replacing insulators over the period from
5 2001 to 2005? If so, provide a copy.

6

7

8 A. 28.1 Please refer to D.W. Reeves testimony, page 9 line 17 to page 10 line
9 19 for the current status of the insulator replacement program.

10

11 Hydro has no formal plan with regards to replacing insulators over the
12 period from 2001 to 2005. Future requirements will be determined
13 through maintenance inspections.