

1 Q. RE: p. B-55 Upgrade – Fuel Storage - Nain (\$339,000)

2

3 38.1 Has a report been prepared on the condition of fuel storage in Nain,
4 and its inability to meet current Storage and Handling of Gasoline and
5 Associated Products? If so, provide a copy.

6

7 A. 38.1 There was no report prepared but there was an engineering review
8 completed. The review revealed that the dyke liner does not extend
9 underneath the three 144,000 liter capacity vertical storage tanks.
10 Also, probable deficiencies in the fuel storage system secondary
11 containment as evidenced by bulges in the dyke liner, apparent water
12 seepage into the dyke and loose connections between the dyke liner
13 and the tanks were noted.

14

15 These tanks were installed in 1974 prior to implementation of the
16 Gasoline and Associated Products Regulations in 1982.