

1 Q. RE: p. B-62 Purchase and Install Uninterruptible Power Supply –  
2 Computer Room (\$70,000)

3

4 43.1 What problems have been experienced with the present  
5 configuration?

6

7

8 A. 43.1 The problems that we have experienced originate with the present  
9 configuration where the servers are supported by a number of  
10 separate UPS that have been installed over a period of years. Over  
11 the past several years, the servers have been replaced with larger  
12 units and upgraded and the present UPS Systems are not able to  
13 supply adequate power conditioning and battery reserve capabilities.  
14 These units are now starting to fail due to battery failures and are in  
15 need of replacement and are no longer adequately protecting the  
16 servers.