Page 1 of 3

Q. Re p. B-10, provide copies of communications from the manufacturer of the 1 2 electronic cards indicating discontinuance of repair and replacement of same by the end of 2004. 3 4 5 A. The following correspondence is attached: 6 7 (a) 8 Letter from Urs Gantenbein, Sulzer Hydro, to Darren Moore (Hydro), dated January 31, 1996, titled Cat Arm Governors. 9 10 11 (b) Fax reply from Urs Gantenbein, Sulzer Hydro, to Rick Leggo, dated January 18, 2000, titled Cat Arm Governor Replacement. 12



Fax

Suizar Canada Inc. 295 boul, Hymus Pointe-Claire Québec Canada H9R 1G6

Telephone (514) 695 - 8320 Telefax (514) 697 - 9862

IC-25

Page 2 of 3

Date January 31, 1996

то Mr. Darren Moore NF & L Hydro Bay d' Espoir

Fax 709 - 882 2707

From Urs Gantenbein

Phone (514) 695 - 8320 Fax (514) 697 9862

No. of pages 1 (including this one) +

CAT ARM - GOVERNORS

(your fax Jan. 15. 1996)

as you indicate, I mentioned in Dec. 1994 that the analog electronic cards used at CAT ARM will soon be obsolete.

SULZER ELECTRONICS, who manufactures the various electronic cards for the whole SULZER Group, was postponing the date when to stop manufacturing the analog electronic cards, therefore we did not yet come back to you with further information.

The following has now been decided: SICOS 1200 - (analog electronic cards for ETR, SM1200 etc.)

- Last sales for new projects by

July 31, 1996

- Advise Sulzer Electronics of demand by

May 31.1996

- Replacement parts available until

end of 2004

- Repair of cards until

end of 2004

NOTE:

SULZER HYDRO - sales will officially inform our clients early 1996

Ps.: (attached find translation of note we received from SULZER HYDRO Switzerland)


Yours sincerely

Urs Gantenbein



P.O. Box 12400 St.John H.Niid. A1841

Ph. (709)737-1212 Fax (709) 737-1972



Nfld. & Labrador

IC-25 Page 3 of 3



	·	Ve			
ie,	Urs Gantenbein, Sulzer Hydro	Afon:	Rick Leggo		•
Fax:	514-697- 9862	Pages:	1		
Phone		Datei	01/18/2000	Jan 18, 3	2900
Re:	Cat Arm Governor Replacement	CC:			
□ Vrlg	ent C For Review x Please Co	mment	☐ Please Reph	√ □ Please Recycl	•
at Cat epiac epiac	nments: I am looking at the need to replate Arm. I have to prepare a report on the end and, if so, when. In an earlier fax froment cards and repair services for the a following information:	condition of m you to D	these controls ar lerren Moore at S	id whether they should lay D'Espoir you said t	be hat
1) s	the 2004 date still valid for the repair of ca	ards? –	o Yes		
5) W	hat do you recommend as a replacement	tand could y			Ge sent
3) W	hat is the estimated cost for the replacem	ent system	ر د- ذ	We will iss	ue a quo
4) M	/hat is the estimated cost for on site assist	tance from S	Sulzer Hydro?	to your pos	TE CLAR
5) M	/hat is the delivery time after receipt of orc	ier?	\sim		
				10 JA	N 2000
Pleas	e call me if you need any further information	on.		, and the second	7-800 TO1
	Dear Rick we will se		0.0 1	W-G-	Jan 18 49
	we will pe	even	the syste	m.	
	you have	and	provide y	oce .	
Thank	Jeggo with a qui	oke for	new	"materials 21/9 (Through Artista) for the	
	hard wark	and	program	mena	
	and instal	lation	at si	Le	
'a l	P8P'ON Regards		, רבור כאט זאכ	المالية	