

1 Q. **Re: p. B-46** Indicate how and by whom the existing control cables were  
2 damaged and what, if any, efforts have been made to recover damages from  
3 the parties responsible.

4

5

6 A. The existing cables were damaged by Hydro staff while erecting the security  
7 fence at the Bay d'Espoir plant. This damage occurred in September 2003  
8 and temporary repairs were made at that time. Since Hydro staff caused the  
9 damages, no efforts were made to recover damages.