

1 Q. **Re: p. B-21** What are the projected inspection and maintenance costs for a  
2 new steel liner for the first six years after its proposed replacement?

3

4

5 A. With a new liner installed in No. 2 stack, the liner inspection frequency will be  
6 changed to a bi-annual event at a cost estimated at \$5,000-\$7,000 per event.

7 Hydro does not anticipate any other maintenance costs on the new liner

8 throughout this six-year period.