

1 **B-23 Replace Fuel Piping, \$529,800**

2 Q. What remediation took place at the Hardwoods gas turbine site in 2005 to
3 address the leaks caused by the corrosion?

4

5

6 A. The underground pipes were replaced by new pipes installed above ground,
7 where they can be visually monitored.