

1 **B-42 Replace Insulators, \$313,000**

2 Q. Provide a copy of a Safety Alert that has been issued regarding insulators
3 that are prone to failure.

4

5

6 A. There has not been a Safety Alert issued. The failure of these insulators was
7 discovered by visual inspection by linesmen from Hydro and other utilities.