B-61	Replace	Distribution	Poles.	\$744.000
D-0 I	IZEDIACE	DISHIDUHUH	r vies.	##.UU

Q. Provide copies of reports resulting from preventative maintenance
inspections that indicate the condition of the poles to be replaced in 2007 in
the three distribution systems included in this project.

A. The condition of the poles is not detailed in a report, but by verbal communications with line crews. The poles in question are almost 40 years old, which is at the end of their normal service life. This information, supplemented by the local crews' patrols/knowledge of the lines in question, assisted us in determining that these structures were required to be replaced by 2007.