

1 **B-65 Replace Diesel Unit 290 & Upgrade Fuel Storage System, Williams**  
2 **Harbour, \$479,300**

3 Q. How and why has this policy changed since 2000?

4

5

6 A. Please refer to PUB 93.0 NLH for an explanation of Hydro's current policy.  
7 Previously, the policy was to overhaul an engine after 15,000 operating  
8 hours, to perform five overhauls and to replace the engine when it required a  
9 sixth overhaul, at approximately 90,000 hours. The policy was changed  
10 because it was found that 5,000 hours could be added to each overhaul  
11 interval without noticeably detracting from the performance of an engine.  
12 This change in policy reduced maintenance costs.