

1 **PUB 3.0**  
2 **(RE: p. 13 & 14 of 82) Penstock Replacement Lockston (\$1,520,000)**

3  
4 **PUB 3.2**

5  
6 **Q. Provide copies of the engineering reports detailing the deteriorating condition of the**  
7 **Lockston Penstock.**

8  
9 A. Attached are copies of the following engineering reports and assessments detailing the  
10 deteriorating condition of the Lockston Penstock:

11  
12 Dam Safety Inspection/Evaluation Reports

13 1. July 1993 (prepared by BAE Group Ltd.), Attachment A.

14  
15 2. November 1995 (prepared by Newfoundland Power), Attachment B.

16  
17 3. June 1997 (prepared by Newfoundland Power), Attachment C.

18  
19 4. November 1999 (prepared by Newfoundland Power), Attachment D.

20  
21 5. December 2000 (prepared by Newlab Engineering), Attachment E.

22  
23 Dam Safety Inspection Checklist

24 6. November 2001 (prepared by Newfoundland Power), Attachment F.