


Re Transformer Cooling Refurbishment, Schedule B, pages 22-23 (\$398,000)

Q. What repairs of the existing transformer radiators have been completed or considered?

A. These radiators are not repairable due to their overall state of deterioration. Temporary repairs (patches) have been used to limit oil leakage and ensure transformer integrity until new radiators could be budgeted, ordered and installed. These patches are not considered to be long-term solutions due to the environmental risk associated with a major spill from a power transformer.

The picture below exhibits temporary repair work on radiators installed on the Greenspond T1 transformer.



15
16