

**Re Distribution Feeder Remote Control, Schedule B, pages 26-27 (\$1,000,000)**

**Q. In the past 5 years, what were the incidents with this equipment that caused environmental hazards and what environmental costs were associated with those incidents?**

**A.** The incidents of leaking or ruptured reclosers in the past five years are provided in Table 1 below. The costs associated with these individual incidents were not tracked.

**Table 1**  
**Spills Involving Reclosers**

<b>Date</b>	<b>Location</b>	<b>Quantity (litres)</b>	<b>PCB Level</b>	<b>Cause</b>
1998/02/17	Bay L'Argent	80	2 mg/kg	Vehicle Accident
2000/11/25	Monkstown	22	< 50 mg/kg	Electrical Burnthrough