

General

Q. Ref: PUB-32 NP. What other alternatives did NP consider besides the full replacement of “deteriorated radiators”.

A. The alternative to replacing the deteriorated radiators is to continue to patch the leaking radiators. However, due to the rusted condition of the radiators and the thin metal as determined by ultrasonic testing, the Company concluded that there was an unacceptable risk to continuing the patching process. Due to the unique construction of the transformer radiators, replacement of part of the radiator is not possible. Replacement radiators are fabricated as complete units.