

General

Q. Ref: PUB-61 NP. Provide the capital expenditure for the refurbishment conducted on the selected distribution lines shown in Table 1.

A. Table 1 provides the capital expenditures for the refurbishment of feeders on which substantial refurbishment was carried out during 1999, 2000 and 2001, as well as the number of customers served by each feeder and the average expenditure per customer.

Table 1				
Feeder #	Location	Capital Expenditure (\$000s)	Customers By Feeder	Expenditures Per Customer (\$)
DUN-01	Branch/St. Brides	1,369	935	1,464
RVH-01	Riverhead/St. Vincents	449	916	490
OPL-01	Old Perlican	1,104	449	2,459
BLK-02	Whitbourne	913	1,086	841
FRN-01	Frenchmans Cove/Benoits Cove	38	758	50
FRN-02	Lark Harbour/York Harbour	638	571	1,117
ROB-01	St. Davids/Robinsons	620	1,082	573
ABC-02	Lourdes/Piccadilly	50	983	51
HOL-01	Holyrood	519	1,793	289
OPL-02	Old Perlican	538	831	647
BLA-01	Bay L'Argent	1,262	1,234	1,023
DOY-01	Doyle's	251	1,500	167
LAU-02	Lawn	716	807	887