1	Q.	Reference: Refurbish Penstock 2, Bay d'Espoir Generating Station, March 3, 2017,
2		Page 2, Lines 15-16.
3		
4		"Based on the condition of the welds in Penstock 1, it is anticipated that the welds in
5		Penstock 2 are in a similar deteriorated state and in need of refurbishment."
6		
7		Please confirm that the justification for this application is based upon the condition
8		of Penstock 1 and not on a condition based assessment of Penstock 2.
9		
10		
11	A.	Yes, the justification for this project is based on the condition of welds identified in
12		Penstock 1. It is reasonable to expect that the welds in Penstock 2 are in similar
13		condition as the welds in Penstock 1 considering the penstocks were constructed by
14		similar design, at approximately the same time, and have been exposed to the same
15		operating environment.