

1 Q. **Volume 1 (1st Revision), Chapter 3: Operations**
 2 Please provide a revised table for Table 3-5 Hydraulic Generation Performance for
 3 the years 2007-2016 that includes a comparison to the national CEA average.
 4 (Volume I (1st Revision), Chapter 3: Operations, Page 3.11, Table 3-5)

5
 6
 7
 8
 9

A. Please refer to Table 3-5 Hydraulic Generation Performance for the years 2007 to 2016.

Table 3-5 Hydraulic Generation Performance – DAFOR (%)

	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016
Hydraulic DAFOR	0.34	1.06	0.69	0.64	0.82	0.95	0.56	5.97 ¹	2.66 ²	5.51 ³
CEA Average⁴	2.7	2.52	1.88	3.93	5.11	4.95	4.95	6.40	6.59	6.51

¹ Failures of two rectifying transformers on Bay d’Espoir Unit 6 contributed 4.90 to the DAFOR.

² Vibration issue on Bay d’Espoir Unit 1 contributed 2.27 to DAFOR.

³ Leaks on the penstock for Bay d’Espoir Units 1 and 2 contributed 5.17 to DAFOR.

⁴ All unit types.