

1 Q. **Tab 12; Volume II: Diesel Genset Replacements (2021-2022)**

2 Please provide a listing, including cost and description of all corrective maintenance performed,
3 since 2015 with respect to Unit 574.

4

5

6 A.

Table 1: Corrective Maintenance Performed Since 2015 – Unit 574

Date	Description	Labour (\$)	Non-Labour (\$)
31-May-2019	Unit Speed Eratic	7,339	611
18-Jan-2019	Replace Hand Fuel Pump	3,527	2,230
22-Oct-2018	Shut Down Oil PSI	605	89
30-May-2018	Install CCV8000	-	3,662
2-Jan-2018	Fuel Pump Leaking	693	-
30-Apr-2017	Repair Oil Leak Turbo	-	388
24-Sep-2016	Fuel Priming PMP	267	473
12-Jul-2016	Replace Fan Motor	813	867
25-Jan-2016	Oil Seal Leak	1,201	1,120
11-Dec-2015	Turbocharger Spare	-	7,210
2-Dec-2015	Investigate Exhaust Temp. Operating	92,023	61,465
19-Nov-2015	Replace Aftercooler	1,743	-
7-Oct-2015	Air Leak from Clamp	-	417
30-Sep-2015	Purchase Injectors	7,208	7,824
28-Sep-2015	Investigate Sparks from Generator	240	-
3-Sep-2015	Unit Unstable/Fuel Issue	1,459	-
30-Jun-2015	Replace Dipstick/T Handle	-	335
28-May-2015	P&C upgrades	39,369	-
27-Mar-2015	Breaker Failure	2,368	661
26-Feb-2015	Replace Oil Filler Cap & Stick	-	211
17-Feb-2015	Investigate Fuel Leak	456	-
3-Feb-2015	Oil Leak Front	2,049	-
22-Jan-2015	Replace Glycol Holding Tank	4,305	2,789