

1 Q. Please confirm that no circumferential welds have been refurbished to date on Penstock 1?

2

3

4 A. Newfoundland and Labrador Hydro (“Hydro”) did complete limited weld refurbishment on
5 circumferential welds, particularly in the early stages of understanding the condition of
6 Penstock 1. Hydro’s efforts have been focused almost exclusively on longitudinal weld seams.