

1 **Re: Replace Unit 2 Air Pre-heater Cold End:**

2 Q. Were rotor shaft seal covers recommended in the Alstom Report?

3

4

5 A. Yes, the installation of rotor shaft seal covers is Item 18 listed under the
6 'Longer Term Recommendations' – Alstom Power Recommendations.

7 Please refer to NLH's *2009 Capital Budget Application*, page C27, Volume I.