

1 **Re: C-124, Replace Conductor on Line 2, Rocky Harbour, \$324,500**

2 Q. When was the most recent visual inspection of the Rocky Harbour L2 feeder
3 undertaken?

4

5

6 A. The most recent visual inspection of the Rocky Harbour L2 feeder was
7 undertaken in January 2008. The inspection revealed that L2 has a strong
8 infrastructure reinforced, as stated in the project submission (see page C-
9 126), by new crossarms and 29 poles replaced in 2007. Other than replacing
10 the conductor, L2 requires no immediate work.