

1 Q. **Re Refurbish Fuel Storage Facility, page B- 8**

2 The report (Volume II, Tab 4) supporting this Project only makes reference to a 2004
3 inspection of Tank 4 conducted by SGE Acres. Has any similar inspection been
4 conducted since the 2004 SGE Acres inspection?

5

6

7 A. No further inspection of Tank 4 has been carried out. The work in 2008 on Tank 2
8 included repairing areas of the tank bottom that tested as substandard.