

1 Q. **Re Replace Pumphouse Motor Control Centres, page B- 12**

2 Have either the safety deficiencies mentioned in paragraph 3.10 of the Report  
3 resulted in any injury to Hydro personnel since the commissioning of these units?  
4

5

6 A. There has been no injury to Hydro personnel since the commissioning of the motor  
7 control centers as a result of the safety deficiencies as listed in Section 3.10.