

1 **Q. In the report provided in Tab 3.1, pg. 2, paragraph 2, NP states that “it is**
2 **recommended that this section of line be rebuilt...at an estimated cost of**
3 **\$1,653,000.” This amount differs from the amount shown on page 1 of the report,**
4 **and included in the total shown in Schedule B, page 27 of 90. Please confirm that**
5 **the amount included in the capital budget for this section of the rebuild is actually**
6 **\$1,853,000.**

7
8 A. It is confirmed that the amount included in the 2012 capital budget for rebuilding sections
9 of the 110L transmission line is \$1,853,000.¹

10
11 The amount of \$1,653,000 stated at page 2, paragraph 2, of the report included at Tab 3.1
12 is in error.

¹ The correct amount of \$1,853,000 is stated in the header of Section 2.1 on page 1, and in Appendix A of the report included at Tab 3.1. It is also included in the project cost total at page 27 of 90 in Schedule B, and included in the 2012 capital budget project cost summaries provided in Schedule A and Schedule B.