

1 Q. Re: Replacement of Stator Windings, Tab 1:

2 Other than age, does Hydro have any reason to suspect that Unit 1 would have
3 similar alignment issues?
4

5

6 A. Unit 1 is of the same vintage, design, and manufacturer as Unit 2, and has been
7 operating in the same environment under very similar conditions, therefore Hydro
8 suspects it is quite possible to find a similar alignment issue. It is not possible to
9 confirm these alignment issues without destructively removing the existing
10 windings. Therefore, it is not practical to check for this prior to rewinding the unit.