

- 1 Q. Re: Upgrade Gas Turbine Control and Monitoring System, Tab 4:
2 Hydro outlines that the last end date was in 2006 for the last cards that were
3 supported. Since that time, have there been any issues with the current system?
4
5
- 6 A. A relay output module, RCM 2030, associated with the programmable logic
7 controller, was replaced in the fall of 2009. No other hardware failures have
8 occurred since then.