

- 1 Q. Re: Upgrade Unit Vibration Monitoring System, Tab 9:
2 Please outline any maintenance issues or failures in the last five years as it relates
3 to the dual channel temperature and ramp differential monitors at the Holyrood
4 plant?
5
6
- 7 A. There have been no maintenance issues with the Dual Channel Temperature and
8 Ramp Differential Monitors.