

1 Q. With reference to the Project **C-20, Upgrade Vibration Monitoring System –**
2 **Holyrood**, have any of the parts identified in Table 1, at page 5, Volume II, Tab 9,
3 been replaced in the service life to date of the TSI system? If yes, identify the part
4 replaced and the year of replacement.

5
6

7 A. Please refer to the following table.

8	<u>Part</u>	<u>Year of Replacement</u>
9	3300/20 Dual Thrust Monitor	2000
10	3300/15 Dual Vibration Monitor	2003
11	3300/40 Eccentricity Monitor	2003
12	3300/20 Dual Thrust Monitor	2004
13	3300/47 Complementary Input Module	2010