

1 Q. With reference to the Project **C-20, Upgrade Vibration Monitoring System –**  
2 **Holyrood**, has Hydro evaluated whether the parts identified in Table 1, at page 5,  
3 Volume II, Tab 9, can be obtained from sources other than Bentley Nevada?  
4

5  
6 A. Other repair facilities exist but Hydro does not have experience with them.  
7 Assuming a compatible facility exists, the outage time related to returning a failed  
8 component applies to the alternate repair facilities as well.