

- 1 Q. (GRA, Volume II, Exhibit 2 - Annual Report on KPIs, page E18)
2 Has Hydro since determined what caused the mobile generator to trip off-line
3 leading to the 5 hour and 48 minute outage at Black Tickle?
4
5
- 6 A. The cause of the mobile generator tripping off-line was determined to be a
7 generator failure. This failure was caused by the severe environmental conditions in
8 Black Tickle, more specifically ocean salt was absorbed into the generator, which
9 resulted in a generator fault.