

1 Q. What was the reason for the 2011 inspection of the Holyrood gas turbine by the  
2 Department of Government Services, Occupational Health and Safety Inspection  
3 Branch (OHS)?  
4  
5

6 A. The primary reason for the 2011 inspection of the Holyrood gas turbine by the  
7 Department of Government Services, Occupational Health and Safety Inspection  
8 Branch (OHS), was concerns around the presence of excess lube oil leaks and risk of  
9 smoke inhalation or fire.