Page 1 of 1

1	Q.	in response to PUB-NLH-U81 from the Island Interconnected System Supply Issues
2		and Power Outages Review, Hydro stated that:
3		However, it was shown that during the events experienced
4		on January 11, 2013, the HWDGT black start contingency
5		plan was inadequate, due to its reliance on the Avalon
6		transmission system.
7		Why was no action taken at that time to ensure adequate black start for Holyrood?
8		Include in the response documentation that illustrates a recognition that the
9		Holyrood plant could be without black start capability.
10		
11		
12	A.	Please see Hydro's response to PUB-NLH-023.