

1    Q.    At page 62 of the Alstom Field Service Report (FSR) 030213 (Appendix C1), it was  
2        stated that "from a mechanical standpoint, there were no findings that would have  
3        prevented the pump from operating effectively." What repairs/actions will be  
4        carried out in Phase 3 of the project to ensure that the DC Oil pump does operate  
5        effectively in the future?

6  
7

8    A.    Until the root cause analysis is completed, the entire scope of work will not be  
9        known. However, Phase 3 of the project will include the work required to ensure  
10        the DC lubricating oil pump operates reliably.