Page 1 of 1

1	Q.	Restoration of Holyrood Unit 1: Please state whether there are any continuing
2		issues with the Holyrood Unit 1 turbine-generator that may have resulted from the
3		damages of January 2013 and whether the vibration issue that persisted through
4		2013 and into 2014 has been eliminated.

A. Following the repairs to the unit in 2013, balancing runs were completed on Unit 1 to bring it within the requirements of unrestricted operation for the winter of 2013/2014. Following the 2014 maintenance outage on Unit 1, further balancing runs were completed, which enabled the unit to be able to go through its start-up sequence more quickly than the experience in 2013/2014, while continuing to meet ISO-7919-2 guidelines for unrestricted, long-term operation. With the maintenance and balancing work carried out, Hydro is confident that Unit 1 can be run in accordance with the ISO guidelines.