

1 Q. Sunnyside and Holyrood Breakers: Please verify that ABCBs SSD B1L03 and HRD  
2 B1B17 were both replaced with SF6 breakers in 2014 and provide the date when  
3 they were replaced.  
4  
5

6 A. In 2014, the air blast circuit breakers HRD B1L17 and SSD B1L03 were replaced with  
7 new SF6 breakers. The HRD B1L17 was placed in-service on October 17, 2014 and  
8 SSD B1L03 was placed in-service on October 24, 2014.  
9

10 Hydro notes that the overhauled parts from the prior B1L17 air blast breaker have  
11 also already been used on another breaker in HRD to ensure winter readiness. In  
12 addition, the overhauled parts for B1L03 air blast breaker in SSD will be re-used in  
13 2015 during air blast circuit breaker overhauls.