PR-PUB-NLH-059 NLH 2015 Prudence Review

Page 1 of 1

L	Q.	Please describe what Hydro determined to be the cause of the maifunction of
2		Western Avalon breaker B1L37.
3		
4		
5	A.	The cause of the malfunction of BL1L37 at WAVTS has not been determined, as the
5		breaker operated correctly following the event.