

1 Q. Please explain why the cost (\$160,900) to repair Sunnyside B1L03 stated in the
2 response to PR-PUB-NLH-30 was included with the "*Sunnyside Replacement*
3 *Equipment*" application approved by Order No. P.U. 29(2014) when this cost was
4 also included in the application for "*Overhaul of the Sunnyside B1L03 230kV Breaker*
5 *and Overhaul of the Holyrood B1L17 230kV Breaker*" approved by Order No. P.U.
6 23(2014).

7
8
9 A. PR-PUB-NLH-030 requested estimated versus actual costs for specific items related
10 to the Sunnyside Replacement Equipment project, approved by Order No. P.U.
11 29(2014), which included item (c), "the repair of the B1L03 230kV breaker at
12 Sunnyside". The repair of the B1L03 breaker was not part of the Sunnyside
13 Replacement Equipment project, but was in fact part of the Overhaul of the
14 Sunnyside B1L03 230 kV Breaker and Overhaul of the Holyrood B1L17 230 kV
15 Breaker project, approved by Order No. P.U. 23(2014) and therefore has not been
16 applied for by Hydro in two separate applications.