

1 Q. Please confirm that a structural engineer considered the effects of Holyrood Unit 1
2 2013 vibrations transmitted to the structure or foundation. If yes, provide a copy of
3 that engineer's report and if no, explain why not.

4

5

6 A. Following the Unit 1 turbine failure, a walk-through of the facility was completed by
7 engineering personnel familiar with the plant, to review the structure and
8 foundations. These personnel found no indication that an external structural
9 engineer would be required to further assess the effects of Holyrood Unit 1
10 vibration on the structure or foundation.