

1 **Q. Re: Tab 1.1 - 2013 Facility Rehabilitation – Soldiers Pond Outlet**

2
3 **When were the lower sections of the gabion wing walls installed and what**
4 **maintenance has been carried out on these over the past 5 years?**
5

6 A. The gabion wing walls were installed in 1993. There has been no maintenance carried
7 out on the lower sections of the gabion wing walls in the last 5 years. The gabion wing
8 walls are constructed from gabion baskets, comprising wire mesh baskets containing
9 large rocks.¹ There are minimal maintenance options for gabion baskets.

¹ Refer to Response to Request for Information CA NP 023 for a photograph of the gabion wing wall.