Q.	Re: Tab 1.4 - Pitmans Pond Hydro Plant Replacement – Turbine
	How long has the turbine seal at Pitmans Pond been leaking?
	The turbine seal began leaking in 2004 and has gotten progressively worse during the past 8 years. In recent years a shield was installed over the turbine seal to contain the leakage.