8

Q. Re: Tab 5.1 - 2013 Company Building Renovations

At p. 2 of the report at Tab 5.1, 5 items are identified as regards the scope of work to be completed in 2013. What is the breakdown of the costs of the 5 items?

A. The estimated cost of the 5 items is provided in Table 1.

Table 1 Carbonear Service Building Renovations

	Item	Estimated Cost
1	Improve Drainage and Install Valves	\$65,000
2	Address Leaks and Repair Exterior Brick	35,000
3	Replace Siding and Roofing	202,000
4	Repair Parking Lot and Walkways	55,000
5	Replace Carpet	18,000
	Total	\$375,000